
1. Disassemble the base.



2. Turn the switch from "BOTH" position to "OFF" position.





3. Screw up the base then test again.



